

INSPECTION REPORT REVIEW
POTENTIAL HAZARDOUS WASTE SITE

SITE NAME : MATERIAL CONTROL INC.
LOCATION : FORT WORTH, TEXAS
SITE NUMBER: TXD000803494
SURVEY DATE: 1980 INSPECTED BY: STATE FIT TAT OTHER: _____
LABORATORY : CLP EPA OTHER N/A

RECEIVED FROM: Betty Williamson

DATE RECEIVED: 09/02/94

SAMPLE TYPE(s): N/A

SOIL	SURFACE WATER	GROUND WATER	DRINKING WATER
off / on -site	off / on -site	off / on -site	off / on -site

CONTAMINANT(s): Organics Inorganics Radionuclides Microbiological N/A

FOLLOW UP (Y/N):

<u>N</u> (Re)Sampling Requested	<u>N</u> Locate Drinking Water Sources
<u>N</u> Further Action is URGENT	<u>N</u> Keep Site Active ("N"=No Further Action)
	<u>Y</u> Concur with Report Recommendations

SUMMARY:

According to the attached information, the site is an active facility and a RCRA non-filer. The source at the site is a landfill which accepts baghouse dust and ferrous smelting waste. Ground water is not used within the target distance limit of the Ground Water Migration Pathway. Drainage from the site and surface water usage within the target distance limit for the Surface Water Migration Pathway is not known.

RECOMMENDATION:

Based on the available information, it appears that the potential for ground or surface water contamination from this site is very unlikely at this time.

Concurrence:

Heidi K. Ray 11/21/94
ENGINEER/REVIEWER

_____/____/____

975968



T349400011